

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
80	084	001	0000006145	See list below	EMC	FMAB-72	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
5500.2021	5500.2024	5500.2107	5500.2110	5500.2113
5500.2022	5500.2025	5500.2108	5500.2111	5500.2114
5500.2023	5500.2106	5500.2109	5500.2112	5500.2115

2 Type of change

Change of product and packaging label due to production transfer from Slovachia (SK) to Romania (RO)

3 Detailed description of change

Change of factory code from SK to TO
Change of origin from SK to RO

Old product label	New product label
	
Old packaging label	New packaging label
	

4 Reason of change

Reorganization of production process.

5 Release date

The change will be rolled-out starting June 2017 and lasts approx. 2 months depending on the variant.

6 Impact of change and recommended action

Form	No	No change in form
Fit	No	No change for dimension
Function	No	No change in function
Production site	Yes	Change of production site
Label	Yes	Change on label
Packaging	No	No change in packaging

Product Change Notification					PCN FMAB-72 Family - Production site		
owner	creation date	release date	released by	change order no	rev	page	D10-016-223
segatro	2017-06-07	2017-06-07	romanogu	2013028	A	1 of 2	

7 Reference Documents / Attachments

Kind of document	Remarks
Datasheet FMAB-72	

Product Change Notification					PCN FMAB-72 Family - Production site		
owner	creation date	release date	released by	change order no	rev	page	D10-016-223
segatro	2017-06-07	2017-06-07	romanogu	2013028	A	2 of 2	