

**End-Of-Life Notice**  
(Notification – CQ-20-05)  
[Issue Date – 12/4/2020]

**To:** Our Valued Customers

**Overview:** The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

**Affected Products:** Attached is a list of products affected by this notification. Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

<b>Key Dates:</b>	Final Last Time Buy (LTB) Orders placed after this date will not be processed.	6/4/2021
	Last Shipment (LTS)	12/4/2021

**Response:** Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas’s General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative for any questions or comments.

Thank you for your attention.

Sincerely,  
Renesas Electronics

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
1339-2DCGI	12/4/2020	6/4/2021	12/4/2021	None
1339-2DCGI8	12/4/2020	6/4/2021	12/4/2021	None
1339-2DVGI	12/4/2020	6/4/2021	12/4/2021	None
1339-2DVGI8	12/4/2020	6/4/2021	12/4/2021	None
2305MI-1HLF	12/4/2020	6/4/2021	12/4/2021	None
2305MI-1HLFT	12/4/2020	6/4/2021	12/4/2021	None
2308A-5HPGG	12/4/2020	6/4/2021	12/4/2021	None
2308A-5HPGG8	12/4/2020	6/4/2021	12/4/2021	None
291PGILF	12/4/2020	6/4/2021	12/4/2021	None
345RPLF	12/4/2020	6/4/2021	12/4/2021	None
345RPLFT	12/4/2020	6/4/2021	12/4/2021	None
445R-34LF	12/4/2020	6/4/2021	12/4/2021	None
445R-34LFT	12/4/2020	6/4/2021	12/4/2021	None
6P40086PGG	12/4/2020	6/4/2021	12/4/2021	None
6P40086PGG8	12/4/2020	6/4/2021	12/4/2021	None
6P40267NLG	12/4/2020	6/4/2021	12/4/2021	None
6P40267NLG8	12/4/2020	6/4/2021	12/4/2021	None
6V40088ENBGI	12/4/2020	6/4/2021	12/4/2021	None
6V40088ENBGI8	12/4/2020	6/4/2021	12/4/2021	None
6V40132PGG	12/4/2020	6/4/2021	12/4/2021	None
6V40132PGG8	12/4/2020	6/4/2021	12/4/2021	None
6V40154PGG	12/4/2020	6/4/2021	12/4/2021	None
6V40154PGG8	12/4/2020	6/4/2021	12/4/2021	None
6V40187PGGW3	12/4/2020	6/4/2021	12/4/2021	None
6V40187PGGW38	12/4/2020	6/4/2021	12/4/2021	None
6V49122PAG	12/4/2020	6/4/2021	12/4/2021	None
6V49122PAG8	12/4/2020	6/4/2021	12/4/2021	None
7152AM-11LF	12/4/2020	6/4/2021	12/4/2021	None
7152AM-11LFT	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543ATPAG	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543ATPAG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543ATPVG	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543ATPVG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543CTPAG	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543CTPAG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543CTPVG	12/4/2020	6/4/2021	12/4/2021	None
74FCT16543CTPVG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT540ATQG	12/4/2020	6/4/2021	12/4/2021	None
74FCT540ATQG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT540ATSOG	12/4/2020	6/4/2021	12/4/2021	None
74FCT540ATSOG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT540CTQG	12/4/2020	6/4/2021	12/4/2021	None
74FCT540CTQG8	12/4/2020	6/4/2021	12/4/2021	None
74FCT540CTSOG	12/4/2020	6/4/2021	12/4/2021	None
74FCT540CTSOG8	12/4/2020	6/4/2021	12/4/2021	None
74SSTUBF32869ABKG	12/4/2020	6/4/2021	12/4/2021	None
74SSTUBF32869ABKG/	12/4/2020	6/4/2021	12/4/2021	None
74SSTUBF32869ABKG8	12/4/2020	6/4/2021	12/4/2021	None
89H12NT12G2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H12NT12G2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H12NT12G2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H12NT12G2ZCHLGI8	12/4/2020	6/4/2021	12/4/2021	None
89H16NT16G2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
89H16NT16G2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H16NT16G2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H16NT16G2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H16T16AG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H16T16AG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H16T16AG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H16T16AG2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H24NT24G2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H24NT24G2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H24NT24G2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H24NT24G2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H24NT6AG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H24NT6AG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H24NT6AG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H24NT6AG2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G2ZCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G2ZCBLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G2ZCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G2ZCBLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G3YCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G3YCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G3YCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32H8G3YCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24AG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24AG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24AG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZBHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZBHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZBHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT24BG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8AG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8AG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8AG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8AG2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8BG2ZCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8BG2ZCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8BG2ZCHLGI	12/4/2020	6/4/2021	12/4/2021	None
89H32NT8BG2ZCHLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12AG2ZCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H48H12AG2ZCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZCBLG8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZCBLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZDBLG	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZDBLG8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZDBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G2ZDBLG8I8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G3YCHLG	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G3YCHLG8	12/4/2020	6/4/2021	12/4/2021	None
89H48H12G3YCHLGI	12/4/2020	6/4/2021	12/4/2021	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
89H48H12G3YCHLGI8	12/4/2020	6/4/2021	12/4/2021	None
89H64H16AG2ZCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H64H16AG2ZCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H64H16G2ZCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H64H16G2ZCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89H64H16G3YCBLG	12/4/2020	6/4/2021	12/4/2021	None
89H64H16G3YCBLGI	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZAEMG	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZAEMG8	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZBEMG	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZBEMG8	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZBEMGI	12/4/2020	6/4/2021	12/4/2021	None
89HMPEB383ZBEMGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZAEMG	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZAEMG8	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZAEMGI	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZAEMGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZBEMG	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZBEMG8	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZBEMGI	12/4/2020	6/4/2021	12/4/2021	None
89HPEB383ZBEMGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES10T4G2ZBBC	12/4/2020	6/4/2021	12/4/2021	None
89HPES10T4G2ZBBC8	12/4/2020	6/4/2021	12/4/2021	None
89HPES10T4G2ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES10T4G2ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES10T4G2ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES12T3G2ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES12T3G2ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES12T3G2ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES16T4AG2ALGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES16T4AG2ALGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES16T4AG2ZCALG	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T3G2ZCALG	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T3G2ZCALG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T3G2ZCALGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T6G2ALGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T6G2ZCALG	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T6G2ZCALG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES24T6G2ZCALGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES3T3ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES3T3ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES3T3ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES3T3ZBBCGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES48H12ZABLG	12/4/2020	6/4/2021	12/4/2021	None
89HPES48H12ZABLGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4G2ZCALG	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4G2ZCALG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4G2ZCALGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4G2ZCALGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES4T4ZBBCGI8	12/4/2020	6/4/2021	12/4/2021	None

<b>Exact Renesas Part # No other variation is being impacted.</b>	<b>Notice Issue Date</b>	<b>LTB / Withdrawn Date</b>	<b>LTS / Obsolete Date</b>	<b>Replacement / Similar / Re-Design</b>
89HPES5T5ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES5T5ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES5T5ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES5T5ZBBCGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T5ZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T5ZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T5ZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T5ZBBCGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T6G2ZCALG	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T6G2ZCALG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T6G2ZCALGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES6T6G2ZCALGI8	12/4/2020	6/4/2021	12/4/2021	None
89HPES8T5AZBBCG	12/4/2020	6/4/2021	12/4/2021	None
89HPES8T5AZBBCG8	12/4/2020	6/4/2021	12/4/2021	None
89HPES8T5AZBBCGI	12/4/2020	6/4/2021	12/4/2021	None
89HPES8T5AZBBCGI8	12/4/2020	6/4/2021	12/4/2021	None
8OSK481GILF	12/4/2020	6/4/2021	12/4/2021	None
8OSK481GILFT	12/4/2020	6/4/2021	12/4/2021	None
8S89200BKILF/W	12/4/2020	6/4/2021	12/4/2021	None
91718CMLF	12/4/2020	6/4/2021	12/4/2021	5P35021B-000NDGI
91718CMLFT	12/4/2020	6/4/2021	12/4/2021	5P35021B-000NDGI8
91730AMLF	12/4/2020	6/4/2021	12/4/2021	None
91730AMLF-PAC	12/4/2020	6/4/2021	12/4/2021	None
91730AMLFT	12/4/2020	6/4/2021	12/4/2021	None
91730AMLFT-PAC	12/4/2020	6/4/2021	12/4/2021	None
932S208DGLF	12/4/2020	6/4/2021	12/4/2021	None
932S208DGLFT	12/4/2020	6/4/2021	12/4/2021	None
932S421CGLF	12/4/2020	6/4/2021	12/4/2021	None
932S421CGLF-SUN	12/4/2020	6/4/2021	12/4/2021	None
932S421CGLFT	12/4/2020	6/4/2021	12/4/2021	None
932S421CGLFT-SUN	12/4/2020	6/4/2021	12/4/2021	None
932S890CKLF	12/4/2020	6/4/2021	12/4/2021	None
932S890CKLFT	12/4/2020	6/4/2021	12/4/2021	None
950201AGLF	12/4/2020	6/4/2021	12/4/2021	None
950201AGLFT	12/4/2020	6/4/2021	12/4/2021	None
951462AGLF	12/4/2020	6/4/2021	12/4/2021	None
951462AGLF-DT0	12/4/2020	6/4/2021	12/4/2021	None
951462AGLFT	12/4/2020	6/4/2021	12/4/2021	None
951462AGLFT-DT0	12/4/2020	6/4/2021	12/4/2021	None
952601EGLF	12/4/2020	6/4/2021	12/4/2021	None
952601EGLFT	12/4/2020	6/4/2021	12/4/2021	None
952906BGLF	12/4/2020	6/4/2021	12/4/2021	None
952906BGLFT	12/4/2020	6/4/2021	12/4/2021	None
954101DGLF	12/4/2020	6/4/2021	12/4/2021	None
954101DGLFT	12/4/2020	6/4/2021	12/4/2021	None
954204CGLF	12/4/2020	6/4/2021	12/4/2021	None
954204CGLFT	12/4/2020	6/4/2021	12/4/2021	None
954206AGLF	12/4/2020	6/4/2021	12/4/2021	None
954206AGLFT	12/4/2020	6/4/2021	12/4/2021	None
954310BGLF	12/4/2020	6/4/2021	12/4/2021	None
954310BGLFT	12/4/2020	6/4/2021	12/4/2021	None
95V847AGLF	12/4/2020	6/4/2021	12/4/2021	None
95V847AGLFT	12/4/2020	6/4/2021	12/4/2021	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
97ULP877BHLF	12/4/2020	6/4/2021	12/4/2021	98ULPA877AHLF
97ULP877BHLF/M	12/4/2020	6/4/2021	12/4/2021	98ULPA877AHLF
97ULP877BHLFT	12/4/2020	6/4/2021	12/4/2021	98ULPA877AHLFT
97ULP877BHLFT/M	12/4/2020	6/4/2021	12/4/2021	98ULPA877AHLFT
9DB401CFLF-INT	12/4/2020	6/4/2021	12/4/2021	None
9DB401CFLFT-INT	12/4/2020	6/4/2021	12/4/2021	None
9LP525BG-2LF	12/4/2020	6/4/2021	12/4/2021	None
9LP525BG-2LFT	12/4/2020	6/4/2021	12/4/2021	None
9LPRS357AKLF	12/4/2020	6/4/2021	12/4/2021	None
9LPRS357AKLFT	12/4/2020	6/4/2021	12/4/2021	None
9LRS3197AKLF	12/4/2020	6/4/2021	12/4/2021	None
9LRS3197AKLFT	12/4/2020	6/4/2021	12/4/2021	None
9LRS4180BKLF	12/4/2020	6/4/2021	12/4/2021	None
9LRS4180BKLFT	12/4/2020	6/4/2021	12/4/2021	None
9UMS9610BKLF	12/4/2020	6/4/2021	12/4/2021	None
9UMS9610BKLFT	12/4/2020	6/4/2021	12/4/2021	None
GX72474-HIU	12/4/2020	6/4/2021	12/4/2021	None
GX74870-JIU	12/4/2020	6/4/2021	12/4/2021	None
INCZLED7001KIT120V	12/4/2020	6/4/2021	12/4/2021	None
INCZLED7001KIT230V	12/4/2020	6/4/2021	12/4/2021	None
MK1727GI-02LF	12/4/2020	6/4/2021	12/4/2021	None
MK1727GI-02LFT	12/4/2020	6/4/2021	12/4/2021	None
SGAS733-FC	12/4/2020	6/4/2021	12/4/2021	None
SMOD705	12/4/2020	6/4/2021	12/4/2021	None
SMOD706	12/4/2020	6/4/2021	12/4/2021	None
SMOD714	12/4/2020	6/4/2021	12/4/2021	None
SMOD729	12/4/2020	6/4/2021	12/4/2021	None
SMOD730	12/4/2020	6/4/2021	12/4/2021	None
SMOD731	12/4/2020	6/4/2021	12/4/2021	None
SMOD731-12C	12/4/2020	6/4/2021	12/4/2021	None
SMOD731-I2C	12/4/2020	6/4/2021	12/4/2021	None
SMOD731-URT	12/4/2020	6/4/2021	12/4/2021	None
SMOD731-USB	12/4/2020	6/4/2021	12/4/2021	None
SMOD732	12/4/2020	6/4/2021	12/4/2021	None
SSTE32882HLBAKG	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG
SSTE32882HLBAKG/M	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG
SSTE32882HLBAKG8	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG8
SSTE32882HLBAKG8/B	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG8
SSTE32882HLBAKG8/M	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG8
SSTE32882HLBAKGI	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG
SSTE32882HLBAKGI8	12/4/2020	6/4/2021	12/4/2021	SSTE32882KB1AKG
TSI350-66CQY	12/4/2020	6/4/2021	12/4/2021	None
TSI381-66IL	12/4/2020	6/4/2021	12/4/2021	None
TSI381-66ILV	12/4/2020	6/4/2021	12/4/2021	None
TSI382-66ILV	12/4/2020	6/4/2021	12/4/2021	None
TSI384-133IL	12/4/2020	6/4/2021	12/4/2021	None
TSI384-133ILV	12/4/2020	6/4/2021	12/4/2021	None
U2780-XS1401D1	12/4/2020	6/4/2021	12/4/2021	None
ZIOL2401STARTERKIT	12/4/2020	6/4/2021	12/4/2021	None
ZLED7000D1DEMOBD	12/4/2020	6/4/2021	12/4/2021	None
ZLED7000KITD1	12/4/2020	6/4/2021	12/4/2021	None
ZLED7000Z11R	12/4/2020	6/4/2021	12/4/2021	None
ZLED7001E1EVB	12/4/2020	6/4/2021	12/4/2021	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ZLED7001KITE1	12/4/2020	6/4/2021	12/4/2021	None
ZMED023 ES	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3027A2V	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3027KITV1P0	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3250AC2V ES	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3250BCEKITV1P0	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3250KITV1P0	12/4/2020	6/4/2021	12/4/2021	None
ZMOD3250TKIT1P0	12/4/2020	6/4/2021	12/4/2021	None
ZMOD4100T	12/4/2020	6/4/2021	12/4/2021	None
ZMOD4410AC1 ESV	12/4/2020	6/4/2021	12/4/2021	ZMOD4410AI1V
ZMOD4410AC1V	12/4/2020	6/4/2021	12/4/2021	ZMOD4410AI1V
ZMOD4410BCKITV1	12/4/2020	6/4/2021	12/4/2021	None
ZMOD4410HCKITV1	12/4/2020	6/4/2021	12/4/2021	ZMOD4410-EVK-HC
ZMOD5201B3KITV1P0	12/4/2020	6/4/2021	12/4/2021	None
ZMOD5201BI3V	12/4/2020	6/4/2021	12/4/2021	None
ZMOD5201BI3V ES	12/4/2020	6/4/2021	12/4/2021	None
ZMOD5201BI5V	12/4/2020	6/4/2021	12/4/2021	None
ZMOD5201BI5V ES	12/4/2020	6/4/2021	12/4/2021	None
ZMOD5220AA1R	12/4/2020	6/4/2021	12/4/2021	None
ZNRG2061AA1R	12/4/2020	6/4/2021	12/4/2021	None
ZNRG2061AA1V	12/4/2020	6/4/2021	12/4/2021	None
ZNRG2061KITV1P0	12/4/2020	6/4/2021	12/4/2021	None
ZSC31210MCREFBV1P1	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3122AA1B	12/4/2020	6/4/2021	12/4/2021	ZSSC3123AA1B
ZSSC3220BI1B	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3220BI2B	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3220BI3R	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3230AC1D ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BC1D-ES
ZSSC3230AC3R ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BC3R
ZSSC3230AC3V ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BC3R
ZSSC3230AI1B ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BI1B
ZSSC3230AI3R ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BI3R
ZSSC3230AI3V ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3230BI3R
ZSSC3240AI1B ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI1B
ZSSC3240AI1D ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI1D-ES
ZSSC3240AI3R ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI3R
ZSSC3240AI3V ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI3R
ZSSC3240BC1B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC1B
ZSSC3240BC1D-ES	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3240BC2B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC2B
ZSSC3240BC3R	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC3R
ZSSC3240BC3R-ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC3R
ZSSC3240BC5B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC5B
ZSSC3240BC6B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CC6B
ZSSC3240BI1B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI1B
ZSSC3240BI1B ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI1B
ZSSC3240BI1D ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI1D-ES
ZSSC3240BI2B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI2B
ZSSC3240BI3R	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI3R
ZSSC3240BI3R-ES	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI3R
ZSSC3240BI3W	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI3W
ZSSC3240BI5B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI5B
ZSSC3240BI6B	12/4/2020	6/4/2021	12/4/2021	ZSSC3240CI6B

<b>Exact Renesas Part # No other variation is being impacted.</b>	<b>Notice Issue Date</b>	<b>LTB / Withdrawn Date</b>	<b>LTS / Obsolete Date</b>	<b>Replacement / Similar / Re-Design</b>
ZSSC3242AI1B ES	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3242AI3R ES	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3242AI3V ES	12/4/2020	6/4/2021	12/4/2021	None
ZSSC3XXXCOMMBDV1P0	12/4/2020	6/4/2021	12/4/2021	None