




PRODUCT OBSOLESCENCE MEMO

GAS DISCHARGE TUBES



Select Bourns® Non-Lead Free Gas Discharge Tube Series to be Discontinued

Riverside, California – January 14, 2025 – In accordance with our ongoing product life cycle management procedures, effective December 31, 2025, Bourns will transfer select Non-Lead Free Gas Discharge Tube Series to an End of Product Life status as follows:

- [2027-xx-5M-xxx](#)
- [2027-xx-xxx](#)
- [2035-xx-5M-xxx](#)
- [2035/2037-xx-xxx](#)
- [2036-xx-5M-xxx](#)
- [2036-xx-xxx](#)
- [2038-xx-5M-xxx](#)
- [2026-xx-xxx](#)

A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is included on the following pages.

The recommended replacement products are provided in the table below with the corresponding obsolete part. The form and function of the recommended replacement part numbers are identical to the obsolete parts. While the fit of the suggested replacement part will not be identical to the obsolete parts due to a difference in device height, the recommended replacement products are pad layout compatible and the specifications of the suggested replacement models are likely to be substitutable for typical applications. Please refer to the Bourns data sheet or contact a Bourns Application Engineer for more information.

Users should test the suggested replacement parts in their specific applications for verification of satisfactory performance. Samples of the suggested replacement parts are available upon request.

Customers may continue to purchase these parts during the End of Product Life transition period between now and December 31, 2025. Orders for these discontinued products during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **December 31, 2025**

Last time ship date: **June 30, 2026**

GDT2501

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2026-07-A1	2026-07-A1LF	2026-23-C2	2026-23-C2LF	2026-30-CB	N/A
2026-07-C	2026-07-CLF	2026-23-C2M136	N/A	2026-35-A	N/A
2026-07-C2	2026-07-C2LF	2026-23-C2F	2026-23-C2FLF	2026-35-A1	2026-35-A1LF
2026-07-C2F	2026-07-C2FLF	2026-23-C2F-CS	N/A	2026-35-A1F	N/A
2026-07-C3	2026-07-C3LF	2026-23-C3	2026-23-C3LF	2026-35-C	2026-35-CLF
2026-07-C4	2026-07-C4LF	2026-23-C4	2026-23-C4LF	2026-35-C2	2026-35-C2LF
2026-07-C4F	N/A	2026-23-C4F-CS	N/A	2026-35-C2F	2026-35-C2FLF
2026-07-C13	N/A	2026-23-C8	N/A	2026-35-C2F-S01	N/A
2026-09-C14	N/A	2026-23-C16M136	N/A	2026-35-C3	2026-35-C3LF
2026-07-C18	N/A	2026-23-CF	N/A	2026-35-C3F	N/A
2026-09-A1	2026-09-A1LF	2026-25-A	N/A	2026-35-C4	2026-35-C4LF
2026-09-C	2026-09-CLF	2026-25-A1	2026-25-A1LF	2026-35-C4F	N/A
2026-09-C2	2026-09-C2LF	2026-25-C	2026-25-CLF	2026-35-C4CF-S01	N/A
2026-09-C2F	2026-09-C2FLF	2026-25-C2	2026-25-C2LF	2026-35-C4F-S01	N/A
2026-09-C3	2026-09-C3LF	2026-25-C2F	2026-25-C2FLF	2026-35-C13F	N/A
2026-09-C4	2026-09-C4LF	2026-25-C2F-F1	N/A	2026-35-C13F-S01	N/A
2026-09-CB	N/A	2026-25-C3	2026-25-C3LF	2026-35-C14F	N/A
2026-15-A	N/A	2026-25-C4	2026-25-C4LF	2026-35-C18	N/A
2026-15-A1	2026-15-A1LF	2026-25-C4F	N/A	2026-35-CF	N/A
2026-15-C	2026-15-CLF	2026-25-C8	N/A	2026-35-CF-S01	N/A
2026-15-C2	2026-15-C2LF	2026-25-CB	N/A	2026-35-CXF-S01	N/A
2026-15-C2F	2026-15-C2FLF	2026-25-CF	N/A	2026-35R-C2F	N/A
2026-15-C3	2026-15-C3LF	2026-26-A1	2026-26-A1LF	2026-40-A	N/A
2026-15-C4	2026-15-C4LF	2026-26-C	2026-26-CLF	2026-40-A1	2026-40-A1LF
2026-15-C14	N/A	2026-26-C2	2026-26-C2LF	2026-40-C	2026-40-CLF
2026-15-CB	N/A	2026-26-C2F	2026-26-C2FLF	2026-40-C2	2026-40-C2LF
2026-20-A	N/A	2026-26-C3	2026-26-C3LF	2026-40-C2F	2026-40-C2FLF
2026-20-A1	2026-20-A1LF	2026-26-C4	2026-26-C4LF	2026-40-C2F-F1	N/A
2026-20-C	2026-20-CLF	2026-30-A1	2026-30-A1LF	2026-40-C3	2026-40-C3LF
2026-20-C2	2026-20-C2LF	2026-30-C	2026-30-CLF	2026-40-C4	2026-40-C4LF
2026-20-C2F	2026-20-C2FLF	2026-30-C2	2026-30-C2LF	2026-40-C8	N/A
2026-20-C3	2026-20-C3LF	2026-30-C2F	2026-30-C2FLF	2026-40-C13F	N/A
2026-20-C4	2026-20-C4LF	2026-30-C3	2026-30-C3LF	2026-40-C18	N/A
2026-23-A	N/A	2026-30-C4	2026-30-C4LF	2026-40-CF	N/A
2026-23-A1	2026-23-A1LF	2026-30-C8	N/A	2026-42-A1	2026-42-A1LF
2026-23-A1F	N/A	2026-30-C14	N/A	2026-42-C	2026-42-CLF

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2026-42-C2	2026-42-C2LF	2027-09-A-HS	N/A	2027-20-SM	2027-20-SMLF
2026-42-C2F	2026-42-C2FLF	2027-09-B	2027-09-BLF	2027-20-SM-RP	2027-20-SM-RPLF
2026-42-C3	2026-42-C3LF	2027-09-C	2027-09-CLF	2027-20-SM-RP2	2027-20-SM-RP2LF
2026-42-C4	2026-42-C4LF	2027-09-B10	2027-09-B10LF	2027-23-A	2027-23-ALF
2026-42-C14	N/A	2027-09-C10	2027-09-C10LF	2027-23-B	2027-23-BLF
2026-47-A	N/A	2027-09-B19	2027-09-B19LF	2027-23-BS	N/A
2026-47-A1	2026-47-A1LF	2027-09-BT1ACD	N/A	2027-23-C	2027-23-CLF
2026-47-C	2026-47-CLF	2027-09-C19	2027-09-C19LF	2027-23-C7	N/A
2026-47-C2	2026-47-C2LF	2027-09-BT1	2027-09-BT1LF	2027-23-B10	2027-23-B10LF
2026-47-C2F	2026-47-C2FLF	2027-09-CT1	2027-09-CT1LF	2027-23-C10	2027-23-C10LF
2026-47-C3	2026-47-C3LF	2027-09-SM	2027-09-SMLF	2027-23-B19	2027-23-B19LF
2026-47-C4	2026-47-C4LF	2027-09-SM-RP	2027-09-SM-RPLF	2027-23-C19	2027-23-C19LF
2026-47-C18	N/A	2027-09-SM-RP2	2027-09-SM-RP2LF	2027-23-BT1	2027-23-BT1LF
2026-50-C2	N/A	2027-15-A	2027-15-ALF	2027-23-BT1-S01	2027-23-BT1-S01
2026-60-A	N/A	2027-15-B	2027-15-BLF	2027-23-CT1	2027-23-CT1LF
2026-60-A1	2026-60-A1LF	2027-15-BH	2027-15-BH	2027-23-SM	2027-23-SMLF
2026-60-C	2026-60-CLF	2027-15-BHW	2027-15-BHW	2027-23-SM-RP	2027-23-SM-RPLF
2026-60-C2	2026-60-C2LF	2027-15-C	2027-15-CLF	2027-23-SM-RP2	2027-23-SM-RP2LF
2026-60-C2F	2026-60-C2FLF	2027-15-B10	2027-15-B10LF	2027-25-A	2027-25-ALF
2026-60-C3	2026-60-C3LF	2027-15-C10	2027-15-C10LF	2027-25-B	2027-25-BLF
2026-60-C3-CEI	N/A	2027-15-B19	2027-15-B19LF	2027-25-C	2027-25-CLF
2026-60-C4	2026-60-C4LF	2027-15-C19	2027-15-C19LF	2027-25-B10	2027-25-B10LF
2026-60-C18	N/A	2027-15-BT1	2027-15-BT1LF	2027-25-C10	2027-25-C10LF
2027-07-A	2027-07-ALF	2027-15-CT1	2027-15-CT1LF	2027-25-B19	2027-25-B19LF
2027-07-B	2027-07-BLF	2027-15-SM	2027-15-SMLF	2027-25-C19	2027-25-C19LF
2027-07-C	2027-07-CLF	2027-15-SM-RP	2027-15-SM-RPLF	2027-25-BT1	2027-25-BT1LF
2027-07-B10	2027-07-B10LF	2027-15-SM-RP2	2027-15-SM-RP2LF	2027-25-CT1	2027-25-CT1LF
2027-07-C10	2027-07-C10LF	2027-20-A	2027-20-ALF	2027-25-SM	2027-25-SMLF
2027-07-B19	2027-07-B19LF	2027-20-B	2027-20-BLF	2027-25-SM-RP	2027-25-SM-RPLF
2027-07-C19	2027-07-C19LF	2027-20-C	2027-20-CLF	2027-25-SM-RP2	2027-25-SM-RP2LF
2027-07-BT1	2027-07-BT1LF	2027-20-B10	2027-20-B10LF	2027-30-A	2027-30-ALF
2027-07-CT1	2027-07-CT1LF	2027-20-C10	2027-20-C10LF	2027-30-B	2027-30-BLF
2027-07-SM	2027-07-SMLF	2027-20-B19	2027-20-B19LF	2027-30-C	2027-30-CLF
2027-07-SM-RP	2027-07-SM-RPLF	2027-20-C19	2027-20-C19LF	2027-30-B10	2027-30-B10LF
2027-07-SM-RP2	2027-07-SM-RP2LF	2027-20-BT1	2027-20-BT1LF	2027-30-C10	2027-30-C10LF
2027-09-A	2027-09-ALF	2027-20-CT1	2027-20-CT1LF	2027-30-B19	2027-30-B19LF

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2027-30-C19	2027-30-C19LF	2027-42-C10	2027-42-C10LF	2035-09-B5	2035-09-B5LF
2027-30-BT1	2027-30-BT1LF	2027-42-B19	2027-42-B19LF	2035-09-BT1	2035-09-BT1LF
2027-30-BT1-S01	2027-30-BT1-S01	2027-42-C19	2027-42-C19LF	2035-09-C5	N/A
2027-30-CT1	2027-30-CT1LF	2027-42-BT1	2027-42-BT1LF	2035-09-SM	2035-09-SMLF
2027-30-SM	2027-30-SMLF	2027-42-CT1	2027-42-CT1LF	2035-09-SM-RP	2035-09-SM-RPLF
2027-30-SM-RP	2027-30-SM-RPLF	2027-42-SM	2027-42-SMLF	2035-09-SM-RP3	2035-09-SM-RP3LF
2027-30-SM-RP2	2027-30-SM-RP2LF	2027-42-SM-RP	2027-42-SM-RPLF	2035-09-SM-RP4	2035-09-SM-RP4LF
2027-35-A	2027-35-ALF	2027-42-SM-RP2	2027-42-SM-RP2LF	2035-15-A	2035-15-ALF
2027-35-A-HS	N/A	2027-47-A	2027-47-ALF	2035-15-B	2035-15-BLF
2027-35-B	2027-35-BLF	2027-47-A-HS	N/A	2035-15-B5	2035-15-B5LF
2027-35-C	2027-35-CLF	2027-47-B	2027-47-BLF	2035-15-BT1	2035-15-BT1LF
2027-35-B10	2027-35-B10LF	2027-47-C	2027-47-CLF	2035-15-SM	2035-15-SMLF
2027-35-C10	2027-35-C10LF	2027-47-B10	2027-47-B10LF	2035-15-SM-RP	2035-15-SM-RPLF
2027-35-B19	2027-35-B19LF	2027-47-C10	2027-47-C10LF	2035-15-SM-RP3	2035-15-SM-RP3LF
2027-35-C19	2027-35-C19LF	2027-47-B19	2027-47-B19LF	2035-15-SM-RP4	2035-15-SM-RP4LF
2027-35-BT1	2027-35-BT1LF	2027-47-C19	2027-47-C19LF	2035-20-A	2035-20-ALF
2027-35-CT1	2027-35-CT1LF	2027-47-BT1	2027-47-BT1LF	2035-20-B	2035-20-BLF
2027-35-SM	2027-35-SMLF	2027-47-CT1	2027-47-CT1LF	2035-20-B5	2035-20-B5LF
2027-35-SM-RP	2027-35-SM-RPLF	2027-47-SM	2027-47-SM	2035-20-BT1	2035-20-BT1LF
2027-35-SM-RP2	2027-35-SM-RP2LF	2027-47-SM-RP	2027-47-SM-RP	2035-20-SM	2035-20-SMLF
2027-40-A	2027-40-ALF	2027-47-SM-RP2	2027-47-SM-RP2	2035-20-SM-RP	2035-20-SM-RPLF
2027-40-B	2027-40-BLF	2027-60-A	2027-60-ALF	2035-20-SM-RP3	2035-20-SM-RP3LF
2027-40-C	2027-40-CLF	2027-60-A-HS	N/A	2035-20-SM-RP4	2035-20-SM-RP4LF
2027-40-B10	2027-40-B10LF	2027-60-B	2027-60-BLF	2035-23-A	2035-23-ALF
2027-40-C10	2027-40-C10LF	2027-60-C	2027-60-CLF	2035-23-B	2035-23-BLF
2027-40-B19	2027-40-B19LF	2027-60-B10	2027-60-B10LF	2035-23-B5	2035-23-B5LF
2027-40-C19	2027-40-C19LF	2027-60-C10	2027-60-C10LF	2035-23-BT1	2035-23-BT1LF
2027-40-BT1	2027-40-BT1LF	2027-60-B19	2027-60-B19LF	2035-23-SM	2035-23-SMLF
2027-40-CT1	2027-40-CT1LF	2027-60-C19	2027-60-C19LF	2035-23-SM-RP	2035-23-SM-RPLF
2027-40-SM	2027-40-SMLF	2027-60-BT1	2027-60-BT1LF	2035-23-SM-RP3	2035-23-SM-RP3LF
2027-40-SM-RP	2027-40-SM-RPLF	2027-60-CT1	2027-60-CT1LF	2035-23-SM-RP4	2035-23-SM-RP4LF
2027-40-SM-RP2	2027-40-SM-RP2LF	2027-60-SM	2027-60-SMLF	2035-25-A	2035-25-ALF
2027-42-A	2027-42-ALF	2027-60-SM-RP	2027-60-SM-RPLF	2035-25-B	2035-25-BLF
2027-42-B	2027-42-BLF	2027-60-SM-RP2	2027-60-SM-RP2LF	2035-25-B5	2035-25-B5LF
2027-42-C	2027-42-CLF	2035-09-A	2035-09-ALF	2035-25-BT1	2035-25-BT1LF
2027-42-B10	2027-42-B10LF	2035-09-B	2035-09-BLF	2035-25-SM	2035-25-SMLF

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2035-25-SM-RP	2035-25-SM-RPLF	2035-47-A	2035-47-ALF	2037-25-B5	2037-25-B5LF
2035-25-SM-RP3	2035-25-SM-RP3LF	2035-47-B	2035-47-BLF	2037-25-BT1	2037-25-BT1LF
2035-25-SM-RP4	2035-25-SM-RP4LF	2035-47-B5	2035-47-B5LF	2037-30-A	2037-30-ALF
2035-30-A	2035-30-ALF	2035-47-BT1	2035-47-BT1LF	2037-30-B	2037-30-BLF
2035-30-B	2035-30-BLF	2035-47-SM	2035-47-SMLF	2037-30-B5	2037-30-B5LF
2035-30-B5	2035-30-B5LF	2035-47-SM-RP	2035-47-SM-RPLF	2037-30-BT1	2037-30-BT1LF
2035-30-BT1	2035-30-BT1LF	2035-47-SM-RP3	2035-47-SM-RP3LF	2037-35-A	2037-35-ALF
2035-30-SM	2035-30-SMLF	2035-47-SM-RP4	2035-47-SM-RP4LF	2037-35-B	2037-35-BLF
2035-30-SM-RP	2035-30-SM-RPLF	2035-60-A	2035-60-ALF	2037-35-B5	2037-35-B5LF
2035-30-SM-RP3	2035-30-SM-RP3LF	2035-60-B	2035-60-BLF	2037-35-C	N/A
2035-30-SM-RP4	2035-30-SM-RP4LF	2035-60-B5	2035-60-B5LF	2037-35-BT1	2037-35-BT1LF
2035-35-A	2035-35-ALF	2035-60-BT1	2035-60-BT1LF	2037-40-A	2037-40-ALF
2035-35-B	2035-35-BLF	2035-60-SM	2035-60-SMLF	2037-40-B	2037-40-BLF
2035-35-B5	2035-35-B5LF	2035-60-SM-RP	2035-60-SM-RPLF	2037-40-B5	2037-40-B5LF
2035-35-C	N/A	2035-60-SM-RP3	2035-60-SM-RP3LF	2037-40-C	N/A
2035-35-BT1	2035-35-BT1LF	2035-60-SM-RP4	2035-60-SM-RP4LF	2037-40-BT1	2037-40-BT1LF
2035-35-SM	2035-35-SMLF	2037-09-A	2037-09-ALF	2037-42-A	2037-42-ALF
2035-35-SM-RP	2035-35-SM-RPLF	2037-09-B	2037-09-BLF	2037-42-B	2037-42-BLF
2035-35-SM-RP3	2035-35-SM-RP3LF	2037-09-B5	2037-09-B5LF	2037-42-B5	2037-42-B5LF
2035-35-SM-RP4	2035-35-SM-RP4LF	2037-09-BT1	2037-09-BT1LF	2037-42-BT1	2037-42-BT1LF
2035-40-A	2035-40-ALF	2037-09-C5	N/A	2037-47-A	2037-47-ALF
2035-40-B	2035-40-BLF	2037-15-A	2037-15-ALF	2037-47-B	2037-47-BLF
2035-40-B5	2035-40-B5LF	2037-15-B	2037-15-BLF	2037-47-B5	2037-47-B5LF
2035-40-BT1	2035-40-BT1LF	2037-15-B5	2037-15-B5LF	2037-47-BT1	2037-47-BT1LF
2035-40-SM	2035-40-SMLF	2037-15-BT1	2037-15-BT1LF	2037-60-A	2037-60-ALF
2035-40-SM-RP	2035-40-SM-RPLF	2037-20-A	2037-20-ALF	2037-60-B	2037-60-BLF
2035-40-SM-RP3	2035-40-SM-RP3LF	2037-20-B	2037-20-BLF	2037-60-B5	2037-60-B5LF
2035-40-SM-RP4	2035-40-SM-RP4LF	2037-20-B5	2037-20-B5LF	2037-60-C	N/A
2035-42-A	2035-42-ALF	2037-20-BT1	2037-20-BT1LF	2037-60-BT1	2037-60-BT1LF
2035-42-B	2035-42-BLF	2037-23-A	2037-23-ALF	2036-07-A	2036-07-ALF
2035-42-B5	2035-42-B5LF	2037-23-B	2037-23-BLF	2036-07-B	2036-07-BLF
2035-42-BT1	2035-42-BT1LF	2037-23-B5	2037-23-B5LF	2036-07-B2	2036-07-B2LF
2035-42-SM	2035-42-SMLF	2037-23-B5-A	N/A	2036-07-B2F	2036-07-B2FLF
2035-42-SM-RP	2035-42-SM-RPLF	2037-23-BT1	2037-23-BT1LF	2036-07-B3	2036-07-B3LF
2035-42-SM-RP3	2035-42-SM-RP3LF	2037-25-A	2037-25-ALF	2036-07-SM	2036-07-SMLF
2035-42-SM-RP4	2035-42-SM-RP4LF	2037-25-B	2037-25-BLF	2036-07-SM-RP	2036-07-SM-RPLF

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2036-07-SM-RP2	2036-07-SM-RP2LF	2036-23-B2F	2036-23-B2FLF	2036-35-C99F-S01	N/A
2036-09-A	2036-09-ALF	2036-23-B3	2036-23-B3LF	2036-35-CF	N/A
2036-09-B	2036-09-BLF	2036-23-B3F	N/A	2036-35-SM	2036-35-SMLF
2036-09-B2	2036-09-B2LF	2036-23-C	N/A	2036-35-SM-RP	2036-35-SM-RPLF
2036-09-B2F	2036-09-B2FLF	2036-23-C2	N/A	2036-35-SM-RP2	2036-35-SM-RP2LF
2036-09-B3	2036-09-B3LF	2036-23-C6F-S	N/A	2036-40-A	2036-40-ALF
2036-09-BSM3-S01	N/A	2036-23-SM	2036-23-SMLF	2036-40-B	2036-40-BLF
2036-09-C	N/A	2036-23-SM-RP	2036-23-SM-RPLF	2036-40-B2	2036-40-B2LF
2036-09-C2	N/A	2036-23-SM-RP2	2036-23-SM-RP2LF	2036-40-B2F	2036-40-B2FLF
2036-09-SM	2036-09-SMLF	2036-25-A	2036-25-ALF	2036-40-B3	2036-40-B3LF
2036-09-SM-RP	2036-09-SM-RPLF	2036-25-B	2036-25-BLF	2036-40-C2	N/A
2036-09-SM-RP2	2036-09-SM-RP2LF	2036-25-B2	2036-25-B2LF	2036-40-SM	2036-40-SMLF
2036-15-A	2036-15-ALF	2036-25-B2F	2036-25-B2FLF	2036-40-SM-RP	2036-40-SM-RPLF
2036-15-B	2036-15-BLF	2036-25-B3	2036-25-B3LF	2036-40-SM-RP2	2036-40-SM-RP2LF
2036-15-B2	2036-15-B2LF	2036-25-B3F	N/A	2036-42-A	2036-42-ALF
2036-15-B2F	2036-15-B2FLF	2036-25-C2	N/A	2036-42-B	2036-42-BLF
2036-15-B3	2036-15-B3LF	2036-25-SM	2036-25-SMLF	2036-42-B2	2036-42-B2LF
2036-15-B99	N/A	2036-25-SM-RP	2036-25-SM-RPLF	2036-42-B2F	2036-42-B2FLF
2036-15-SM	2036-15-SMLF	2036-25-SM-RP2	2036-25-SM-RP2LF	2036-42-B3	2036-42-B3LF
2036-15-SM-RP	2036-15-SM-RPLF	2036-30-A	2036-30-ALF	2036-42-B9	N/A
2036-15-SM-RP2	2036-15-SM-RP2LF	2036-30-B	2036-30-BLF	2036-42-C2	N/A
2036-20-A	2036-20-ALF	2036-30-B2	2036-30-B2LF	2036-42-C2F	N/A
2036-20-B	2036-20-BLF	2036-30-B2F	2036-30-B2FLF	2036-42-SM	2036-42-SMLF
2036-20-B2	2036-20-B2LF	2036-30-B3	2036-30-B3LF	2036-42-SM-RP	2036-42-SM-RPLF
2036-20-B2F	2036-20-B2FLF	2036-30-C2	N/A	2036-42-SM-RP2	2036-42-SM-RP2LF
2036-20-B3	2036-20-B3LF	2036-30-SM	2036-30-SMLF	2036-47-A	2036-47-ALF
2036-20-C2	N/A	2036-30-SM-RP	2036-30-SM-RPLF	2036-47-B	2036-47-BLF
2036-20-SM	2036-20-SMLF	2036-30-SM-RP2	2036-30-SM-RP2LF	2036-47-B2	2036-47-B2LF
2036-20-SM-RP	2036-20-SM-RPLF	2036-35-A	2036-35-ALF	2036-47-B2F	2036-47-B2FLF
2036-20-SM-RP2	2036-20-SM-RP2LF	2036-35-B	2036-35-BLF	2036-47-B3	2036-47-B3LF
2036-23-A	2036-23-ALF	2036-35-B2	2036-35-B2LF	2036-47-B9	N/A
2036-23-AM	N/A	2036-35-B2F	2036-35-B2FLF	2036-47-C2	N/A
2036-23-B	2036-23-BLF	2036-35-B3	2036-35-B3LF	2036-47-SM	2036-47-SMLF
2036-23-BC2F	N/A	2036-35-B4	N/A	2036-47-SM-RP	2036-47-SM-RPLF
2036-23-BSM3-S02	N/A	2036-35-BF	N/A	2036-47-SM-RP2	2036-47-SM-RP2LF
2036-23-B2	2036-23-B2LF	2036-35-C2	N/A	2036-60-A	2036-60-ALF

Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers	Affected Part Numbers	Suggested Replacement Part Numbers
2036-60-B	2036-60-BLF	2038-110-SM	2038-110-SM	2038-47-SM	2038-47-SM
2036-60-B2	2036-60-B2LF	2038-110-SM-RP	2038-110-SM-RP	2038-47-SM-RP	2038-47-SM-RP
2036-60-B2F	2036-60-B2FLF	2038-110-SM-RP2	2038-110-SM-RP2	2038-47-SM-RP2	2038-47-SM-RP2
2036-60-B3	2036-60-B3LF	2038-35-SM	2038-35-SM	2038-60-SM	2038-60-SM
2036-60-B9	N/A	2038-35-SM-RP	2038-35-SM-RP	2038-60-SM-RP	2038-60-SM-RP
2036-60-C2	N/A	2038-35-SM-RP2	2038-35-SM-RP2	2038-60-SM-RP2	2038-60-SM-RP2
2036-60-SM	2036-60-SMLF	2038-42-SM	2038-42-SM	2038-80-SM	2038-80-SM
2036-60-SM-RP	2036-60-SM-RPLF	2038-42-SM-RP	2038-42-SM-RP	2038-80-SM-RP	2038-80-SM-RP
2036-60-SM-RP2	2036-60-SM-RP2LF	2038-42-SM-RP2	2038-42-SM-RP2	2038-80-SM-RP2	2038-80-SM-RP2

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).