



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

To: Littelfuse Sales, Sales Support & Valued Customers

From: Littelfuse Product Management – Industrial Business Unit

Subject: Serie Obsolescence: FLSR.100TXID-FLSR.800TXID, LSRK.100TXID-LSRK.800TXID & IDSR.100T-IDSR.800T

Document Number: LFPCN_PG0197

Date: Rev 10/28/2024

This notice is to inform Littelfuse Sales, Sales Support & Customers of the obsolescence of these series: FLSR .100-.800 (TXID), LSRK .100-.800 (TXID) & IDSR .100-.800 (T), due to obsolesce of raw material components. Attached is the list of part numbers.

This change will be effective immediately

Thank you for your continued business. If you have any questions, or need additional information please contact your Littelfuse representative.

Sincerely,

Zuleyma Davila

Associate Product Manager

Industrial Business Unit

Littelfuse, Inc.

Office: +52 878-782-6222

Techline: +1 800-TEC-FUSE

www.littelfuse.com/electrical

List of items

FLSR.100TXID
FLSR.150TXID
FLSR.200TXID
FLSR.250TXID
FLSR.300TXID
FLSR.400TXID
FLSR.500TXID
FLSR.600TXID
FLSR.800TXID
LSRK.100TXID
LSRK.150TXID
LSRK.200TXID
LSRK.250TXID
LSRK.300TXID
LSRK.400TXID
LSRK.500TXID
LSRK.600TXID
LSRK.800TXID
IDSR.100T
IDSR.150T
IDSR.200T
IDSR.250T
IDSR.300T
IDSR.400T
IDSR.500T
IDSR.600T
IDSR.800T