



20<sup>th</sup> Jun. 2024

To: Valued Customers

From: Littelfuse Product Management

Subject: Immediate EOL of certain Fuse Holders and Specialty Fuses

As regards to the above reference, due to low/zero volumes and product rationalization, Littelfuse will be phasing out certain Fuse Holders and Specialty Fuses with immediate effect.

We will not be able to support any new orders going forward.

As regards to existing open orders in the system today, we will support.

Part numbers affected are shown on the next page.

Please let us know should you have further queries.

Best Regards;

Style Liu  
Global Product Manager  
SLiu@Littelfuse.com  
Tel - +86 512 67613189-2251

01290001H	65600001029	01550106HXU	03452HS7X	0481.375H	344862-010
01290002H	65616301600	01550106ZXA	03452HS8H	0481.375HXL	344864-010
03440402X	66000001109	01550109ZXA	03452HS8X	0481.375HXM	344865-010
01500322HXGRE	82000000025	01550109ZXU	03452LF1H	0481.375V	FB66C1
01500322HXRED	82400000205	01550114ZXU	03452LS1H	0481.375VXL	FC51E
03440805Z	85700001009	01550312ZXA	03452LS1HXL	0481.650H	FC51E-2
03440006X	00BS0232MXBL	01550312ZXU	03452LS3H	0481.650HXL	FC51FLT
03440401X	01020064H	01550435ZXA	03452LS4H	0481.650HXM	FH604R
00300210H	01020064Z	01550440ZXA	03452LS7H	0481.650V	LH61A800
FC61D	01020079H	01550445ZXA	03452LS8H	0481.650VXL	01110503Z
FB58B	01030001Z	02450002X	03452QS1H	0481.750H	01230001Z
81300000005	01050013H	02450002XXL	03452QS2H	0481.750HXL	OPTF0030M
82000000205	01210004H	02450002XXLN	03452QS3H	0481.750HXM	FB55
FH602R	01210004Z	02450002XXN	03452QS4H	0481.750V	
03440804Z	01220055Z-1	02540131Z	03452QS7H	0481.750VXL	
OPTF015BP	01250004H	0269.002V	03452QS8H	04820004ZXBFH	
01010003Z	01500080Z	02700181U	03453LF1ZX020	04820005ZXBFH	
03452LS2H	01500145HXB	02800002ZXA	03453LS2ZNA	04820012ZXBFH	
01550014ZXU	01500261Z	02800004Z	03455RF2ZL	04820016ZXPRT	
01040002Z	01500274ZXG	02800024Z	03480002Z	04820102ZXB	
82400000005	01500278Z	0280002ZXA	03480003Z	04820103ZXB	
FH602S	01500284Z	02820001ZXA	03480004Z	04820104ZXB	
FH503S	01500308Z	03400338H	03480007ZXS10	0482HAD1HXP	
01290002Z	01500315Z	03420010HX010	03480007ZXS12	05200001H	
03452LS1HX020	01500316Z	03440403H	03480007ZXS15	09050041H	
FC61BA	01500317Z	03440605Z	03480007ZXS7	0HBC6X25HX125V30AZ	
FC61F	01500318Z	03440853ZX020	03480007ZXS8	0OMN0002XXFUS	
01290001Z	01500319Z	03440854ZX010	03480009ZXS8	0OMN0004XXFUS	
904216001	01500322.HXU	03440855ZX010	03480670Z	0OMN0006XXFUS	
56800000015	01500322HXBLU	03440856ZX010	03480871Z	OPTF0010P	
58600000015	01500323Z	03450913HXQC040	03480877X	OPTF0015P	
64000001403	01500324Z	03452HS1H	03540912ZXBL	OPTF0020P	
64000001903	01500325Z	03452HS1X	035900010Z	OPTF0035M	
64601257133	01500604Z	03452HS2H	03590010Z	OPTF0040M	
64601607163	01500605Z	03452HS2X	04450004LXN	OPTF0055M	
64613157151	01530019X	03452HS3H	04450023H	OPTF0065W	
64613157153	01550006ZXA	03452HS3X	04450023N	OPTF0070M	
64616307173	01550014ZXA	03452HS4H	04450702H	OPTF0077P	
64616307183	01550100XBP	03452HS4X	04450726MA	OPTF0080M	
64800001001	01550104ZXA	03452HS7H	04450736Z	OPTF015SP	