



## California Proposition 65 Statement

Company Name: Harwin plc

Company Address: Fitzherbert Road, Farlington, Portsmouth, Hampshire.  
PO6 1RT. UK

Contact Person: Martin J Perry

E-mail: complianceteam@harwin.com

Telephone: +44 (0)2392 314545

### Product Information:

See attached part number list.

This letter is to inform the reader that the above-mentioned product(s) made by the above-mentioned company do contain the following CA Prop 65 substance(s):

Antimony Trioxide (1309-64-4) within plastic moulding.

Beryllium (7440-41-7) within BeCu contacts.

Lead (7439-92-1) within Brass.

Nickel (CAS No: 7440-02-0) plating.

See attached part number list for details.

CA Prop 65 substances can be found at:

<https://oehha.ca.gov/proposition-65/proposition-65-list>

A handwritten signature in black ink that reads "M. J. Perry". The signature is written in a cursive style with a large, looping flourish at the end.

Signature:

Name: Martin J Perry

Title: Product Environmental Compliance Specialist

Date: 13<sup>th</sup> June, 2024.

<u>Part Number</u>	<u>Antimony Trioxide</u>	<u>Beryllium</u>	<u>Lead</u>	<u>Nickel</u>	<u>Corrected Harwin PN</u>
-	<u>(1309-64-4)</u>	<u>(7440-41-7)</u>	<u>(7439-92-1)</u>	<u>(7440-02-0)</u>	-
<u>G125-MS11605L3P</u>	-	-	-	<u>YES</u>	-
<u>M20-9740346</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9770246</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9770842</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9980345</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9980445</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9990245</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9990246</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M20-9990745</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M22-2015005</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M22-2020305</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M300-MV30645M1</u>	-	-	<u>YES</u>	<u>YES</u>	-
<u>M50-3500542</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M50-3501042</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M50-3600542</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M50-3601042</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M50-3601042R</u>	<u>YES</u>	-	-	<u>YES</u>	-
<u>M55-7012642R</u>	-	-	-	<u>YES</u>	-
<u>M80-001</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-0030006</u>	-	-	-	<u>YES</u>	-
<u>M805000000M104331</u>	-	<u>YES</u>	<u>YES</u>	<u>YES</u>	<u>M80-5000000M1-04-331-00-000</u>
<u>M805000000M204331</u>	-	<u>YES</u>	<u>YES</u>	<u>YES</u>	<u>M80-5000000M2-04-331-00-000</u>
<u>M80-5000842</u>	-	-	-	<u>YES</u>	-
<u>M80-5001042</u>	-	-	-	<u>YES</u>	-
<u>M80-5002042</u>	-	-	-	<u>YES</u>	-
<u>M80-5003442</u>	-	-	-	<u>YES</u>	-
<u>M80-5004242</u>	-	-	-	<u>YES</u>	-
<u>M80-5100642</u>	-	-	-	<u>YES</u>	-
<u>M80-5101042</u>	-	-	-	<u>YES</u>	-
<u>M80-5102042</u>	-	-	-	<u>YES</u>	-
<u>M80-5104242</u>	-	-	-	<u>YES</u>	-
<u>M80-5121042</u>	-	-	-	<u>YES</u>	-
<u>M80-5122642</u>	-	-	-	<u>YES</u>	-

<u>M80-5401005</u>	-	-	-	<u>YES</u>	-
<u>M805T10605M102331</u>	-	<u>YES</u>	<u>YES</u>	<u>YES</u>	<u>M80-5T10605M1-02-331-00-000</u>
<u>M805T10805M102331</u>	-	<u>YES</u>	<u>YES</u>	<u>YES</u>	<u>M80-5T10805M1-02-331-00-000</u>
<u>M80-6660442</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-6660842</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8280442</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8280642</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8280842</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8281042</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8281242</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8520342</u>	-	-	-	<u>YES</u>	-
<u>M80-8520642</u>	-	-	-	<u>YES</u>	-
<u>M80-8530642</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8540842</u>	-	-	-	<u>YES</u>	-
<u>M80-8820342</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>M80-8820642</u>	-	<u>YES</u>	-	<u>YES</u>	-
<u>S1751-46</u>	-	-	-	<u>YES</u>	-
<u>S1751-46R</u>	-	-	-	<u>YES</u>	-